Report Number: 35689 Report Date: 2011-09-13

Laboratory Report

Report prepared for:

Larry Clark Enviro Tech Europe LTD 216 King Cotton Rd Brunswick, GA 31525 Phone: 912-399-1559

Email: svgoliard@gmail.com

Report prepared by:

William M Longmire

Purchase Order:

VISA,Clark,8/26/11

For further assistance, contact:

William M Longmire
Vice President of Technical Services
PO Box 51610
Knoxville, TN 37950-1610
(865) 546-1335
williamlongmire@galbraith.com

•	Super Corr"A" proprietary base material 2011-P-0837	Received:	2011-08-26		
Analysis	Method	Result	Basis	Amount	Date (Time)
104: Flashpoint,Pensky Martens					
	ASTM D93-10a	No Flash Observed	As Received	Direct	2011-09-01
105: Flashpoint, Cleveland OC					
	ASTM D92-05a	No Flash Observed	As Received	Direct	2011-09-07
107: Flashpoint, Tag Closed Cup					
	ASTM D56-05	No Flash Observed	As Received	Direct	2011-09-08

For all samples on this report:

1. The sample enhanced the test flame, but did not give a true flash point as defined in ASTM D92,D93, or D56.

Signatures:

Published By: william.m.longmire

2011-09-13T16:28:34.387-04:00

- Physical signatures are on file.
- "Published By" signature indicates authorized release of data.